Michael O. Leavitt Kathleen Clarke **Executive Director** Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)



Partial XX	XX Complete _	Exploration
Inspection Date:	07/31/2002 / Ti	me: <u>9-10:15 AM</u>
		ction: 06/27/2002

Mine Name: <u>Centennial Project</u>	County: Carbon Permit Number: C/007/019						
Permittee and/or Operator's Name: Andalex Resources, Inc.							
Business Address: P.O. Box 902, Price, Utah 84501							
Company Official(s): Mr. Mike Glasson, Senior Geologist							
State Official(s): Peter Hess	Federal Official(s): None						
Weather Conditions: Partly sunny; warm; 80's Fahrenheit.							
Type of Mining Activity: Underground	Surface Prep Plant Other						
Existing Acreage: Permitted 5419.49 Dis	turbed 35.27 Regraded Seeded Seeded						
Status: Active -							

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<b>EVALUATED</b>	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	[_]
2.	SIGNS AND MARKERS	[X]			
3.	TOPSOIL				$\Box$
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]		[X]	
b.	SEDIMENT PONDS AND IMPOUNDMENTS	$\overline{[X]}$		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES	[X]	- [_]		
d.	WATER MONITORING	[X]		[X]	
e.	EFFLUENT LIMITATIONS		[_]	$\Box$	
5.	EXPLOSIVES				
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		[X]		
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		[X]		
8.	NONCOAL WASTE	[X]	<u> [_]</u>	$\Box$	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE		[X]		
11.	CONTEMPORANEOUS RECLAMATION				
12.	BACKFILLING AND GRADING		[X]		
13.	REVEGETATION		[X]		
14.	SUBSIDENCE CONTROL				
15.	CESSATION OF OPERATIONS				
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]			
b.	DRAINAGE CONTROLS	[X]			. [_]
17.	OTHER TRANSPORTATION FACILITIES	[X]			
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]		[ <u>X</u> ]	ГŢ
19.	AVS CHECK (4th Quarter- April, May, June)		. [_]		
20.	AIR QUALITY PERMIT				ГŢ
21.	BONDING & INSURANCE	[_]			$\sqcup$

### INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/019</u> DATE OF INSPECTION: <u>07/31/2002</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

Note: The permittee continues with the refurbishing of the conveyor system in the Aberdeen Mine. Mr. Glasson anticipates that production in that mine will resume in September.

# 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee recently submitted a revised legal description to include the Mathis lease into the Centennial Mine permit area. The verification of that description is pending within the Division.

## 4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversion ditch designated as DD-3 (parallels primary road designated as PR-1) was observed to contain more rubble from the sloughage of the cut bank than was felt to be appropriate. Mr. Glasson agreed to address this issue.

## 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

All sediment ponds were observed as dry. No problems were noted.

## 4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee has not initiated the third quarter 2002 water monitoring requirements for the Centennial permit area.

### 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The permittee is upgrading the mine's ventilation system with a new 2,000 horsepower fan, which is located in the left hand fork of Deadman Canyon. An installation crew from Electrical Contactors, Inc. was wiring in the new motor during today's field inspection. There are no changes in the amount of disturbance, or in sediment control methods for this upgrade.

Inspector's Signature:

Peter Hess

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

Date: July 31, 2002

cc:

Note:

James Fulton, OSM

Mike Glasson, Andalex

Price Field office

O:\007019.CEN\Compliance\2002\p 0731.doc